For Continuation of 40 Wires as Shown - See Drwg. PX-5-116
55 Tubes (For 22 Heater Wires See Drwg. PX-5-116)
M
L
K
J
H
G
F
E
D
C
B
A
To Drawing PX-5-105
To Drawing PX-5-116
SP
PQ
PR
PS
Moore School of Electrical Engineering
University of Pennsylvania