


- BELL } INDICATE WHEN THERMOSTATS HAVE OPENED. MACHINE
- LAMP } WILL THEN STOP IN TIME SHOWN ON P TIMER
- LAMP LIT ON P.S. FIL. FUSE FAILURE
- LAMP LIT ON D.C. FAILURE OR D.C. STOP



REVISIONS
 F & P TIMERS REVISED,
 Q RELAYS, INDICATING
 LAMPS & BELL ADDED.
 J. Cummings 1-30-46 1

MOORE SCHOOL OF ELECTRICAL ENGINEERING UNIVERSITY OF PENNSYLVANIA			
<i>A.C. POWER DISTRIBUTION RACK</i>			
MATERIAL	FINISH	SCALE	
Drawn by J. CUMMINGS 12-21-45	CHECKED BY J. CUMMINGS 12-21-45	APPROVED BY:	PX-1-304