


- Pin Connections**
- 1 - Clear Input
 - 2 - #1 Clear Output
 - 3 - #2 Clear Output
 - 4 - 100V
 - 5 - 40V
 - 6 - 20V
 - 7 - 110V
 - 8 - 110V
 - 9 - 110V
 - 10 - 110V
 - 11 - 110V
 - 12 - 110V AC
- Pin Connections**
- 1 - Initial Clear
 - 2 - Clear Gate
 - 3 - Input from receiver for clearing decade 1 through 4
 - 4 - 295V
 - 5 - 230V
 - 6 - 45V
 - 7 - 235V
 - 8 - 180V
 - 9 - 110V
 - 10 - 16V
 - 11 - 110V AC
 - 12 - 110V AC
- * See PX5-145



ENIAC SECTION - COMPUTING UNIT
 PARTIAL ACCUMULATOR CLEARING UNIT
 Form 7-14-49, SMO
 Applies to
PX4143