


PX-1-316

DIGIT TRAY CONNECTIONS



205731

FIG. B-1
SCHEMATIC DRAWING OF PROGRAM SET-UP
FOR GENERATING n^2

117A