



ST	
1	STEP. IN. BUS
2	STEP. DIR. IN.
3	+20
4	GIG. GATE IN. IN.
5	+25
6	CPP
7	+110
8	PULSE OUTPUT
9	PROG. INPUT
10	+225
11	+50
12	+75

SW	
1	PULSE INPUT
2	+20
3	OUTPUT #3
4	TRANS. GATE #3
5	OUTPUT #2
6	TRANS. GATE #2
7	OUTPUT #1
8	TRANS. GATE #1
9	+225
10	+50
11	+75
12	

SBM	
1	To SAA1
2	SAA2
3	SAA3
4	SAA4
5	SAA5
6	SAA6
7	SAA7
8	SAA8
9	SAA9
10	SAA10
11	SAA11
12	GROUND

SBN	
1	To SAA1
2	SAA2
3	SAA3
4	SAA4
5	SAA5
6	SAA6
7	SAA7
8	SAA8
9	SAA9
10	SAA10
11	SAA11
12	GROUND

SU	
13	+150
14	+460
15	-75
16	

SV	
1	H5
2	H18
3	H4
4	H6
5	
6	+225 H18
7	+220 H17
8	H17
9	-130
10	-85 H5
11	+260
12	+370

SX	
1	+35 H19
2	H19
3	H4
4	-130 H4
5	
6	+230
7	H4B
8	H4B RT
9	H4A
10	H4A, H6A
11	
12	

REVISIONS

1	REVISED BY: [Signature]
2	REVISED BY: [Signature]
3	REVISED BY: [Signature]
4	REVISED BY: [Signature]
5	REVISED BY: [Signature]

MOORE SCHOOL OF ELECTRICAL ENGINEERING
UNIVERSITY OF PENNSYLVANIA

H. P. [Signature] M. T. [Signature] J. S. [Signature] P. [Signature]

C. J. Mc. [Signature] [Signature] [Signature] [Signature] PX-8-11

APR 16, 1954